


## 18GN110



300181





#### **Technical data**

Name	Clearing trolley 18GN110 for GN containers, GN baking trays, and trays	
Code-No.:	300181	
Material:	Nickel-chrome steel	
Realization:	<ul> <li>Frame: pipes of square section 25.8 x 25.8 mm;</li> <li>Capacity: 18 GN containers 1/1 GN, depth 65 mm;</li> <li>One front and one back container lock;</li> <li>4 swivelling rubber castors, Ø 100 mm, each with 1 buffer, 2 swivelling castors with stoppers;</li> <li>Easy assembling kit</li> </ul>	
Dimensions:	W 415 x D 610 x H 1890 mm	
Maximum carrying capacity:	80 kg in total, 10 kg per slot	
Distance between slots:	80 mm	
Weight:	20.2 kg	

- Unpack the individual elements and remove the packaging material.
- Check completeness of delivery according to the list below.



### **Delivery range / Part name**

Element	Number	Name
	2	Side parts with 18 preinstalled guides and 1 container lock per each one
	6	Cross members
	2	Castors with stoppers
	2	Castors without stoppers
0	4	Buffers for castors
~	1	Allen wrench
Ø	20	Square washers
~	12	Bolts



#### **Assembly**






Fig. 1

- First, install 6 cross members (upper, lower and middle) to one side part of the clearing trolley (fig. 1).
  - Place a square washer between the upper cross member and side part, lower cross member and side part, and between the side part and each bolt, and tighten those elements with use of an Allen wrench.
  - With the middle cross members, place a square washer only between the side part and bolt, and tighten those elements with use of an Allen wrench.
- Connect 6 cross members with another side part with use of washers and bolts as above.



Place the clearing trolley on its side and attach the buffers for castors to the side parts. Finally, screw the castors into the side parts.

Fig. 2



# **B**artscher

#### **Protection of containers**

 Put the containers in the guides as required and protect them with use of front and back locks, lifting them a bit and placing before the containers (fig. 4).



Fig. 4

#### **Cleaning instructions**

- The clearing trolley should be periodically cleaned with use of moistened and soft cloth.
- Never use any cleaning agents which may scratch the trolley elements surfaces.
- Dry the clearing trolley with soft cloth.

Bartscher GmbH Franz-Kleine-Str. 28 33154 Salzkotten Germany

phone: +49 (0) 5258 971-0 fax: +49 (0) 5258 971-120